


Niagara Air Parts, Inc.

2221 Niagara Falls Blvd., Niagara Falls, New York, 14304

Ph: 800-565-4268 Fax 705-326-8105 Int: 705-326-1368

E – mail: sales@niagaraairparts.com Website: niagaraairparts.com

1971890 Rebuilt Pull Start Clutch



Fits all small C-75, 85, 90, 0-200 & 0-300 Continental engines configured for a Pull Starter.

FAA / STC

**4 rollers, has tendency to square the pinion gear
Holes drilled for spring placement tend to crack**

Warranty

Six (6) months or 100 hours tach time which ever comes first.

No warranty against cracking